

TRIAD
Extreme UNIVERSAL



HEAT: 500 °C
SPEED: 40%

T3
Extreme



HEAT: 430 °C
SPEED: 4

T300
Extreme



Hot Air Welding
HEAT: 500 °C
SPEED: 4 M/MIN

Hot Wedge Welding
HEAT: 450 °C
SPEED: 5 M/MIN


T600
Extreme



Hot Air Welding
HEAT: 500 °C
SPEED: 4 M/MIN

Hot Wedge Welding
HEAT: 450 °C
SPEED: 5 M/MIN

112
Extreme



HEAT: 730 °C
SPEED: 10 M/MIN

***All published weldi settings are estimate ranges. The settings of your machine may vary greatly.
The testing of all seams and all fabrics is the exclusive responsibility of the operator.